

Inspection Photos
Location Name: Simpson A#9
Location ID: 319940



Photo#1 Production Tanks



Photo#2 Stained Soil behind SW Production Tank

Inspection Photos
Location Name: Simpson A#9
Location ID: 319940



Photo#3 Stained Soil behind SW Production Tank



Photo#4 Produced Water Tank (NO BBL markings and identification labels).

Inspection Photos
Location Name: Simpson A#9
Location ID: 319940



Photo#5 **Unused Equipment next to open pit**

Photo#6 **Earthen Pit**

Inspection Photos
Location Name: Simpson A#9
Location ID: 319940



Photo#7 Earthen Pit #2



Photo#8 Unused equipment (ECD)

Inspection Photos
Location Name: Simpson A#9
Location ID: 319940



Photo#9 (2) Vertical Separators/Propane Tank/Buffer Tank



Photo#10 Simpson A#9 Wellhead/Pumpjack

Inspection Photos
Location Name: Simpson A#9
Location ID: 319940



Photo#11 Gas Meter

