

Inspection Photos

8/4/2023

Operator: LARAMIE ENERGY LLC #10433

Location Number: 383264

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



August 4, 2023

Photo 1: Photo shows Porta-johns have been secured to prevent a spill.



August 4, 2023

Photo 2: Photo shows Operator has installed a berm at the toe of the drill cuttings stockpiled on the north end of the Location. Berm has been installed in a manner that is inadequate to contain/prevent a spill. BMP also largely unconsolidated material.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



August 4, 2023

Photo 3: Photo shows Operator has installed a berm at the toe of the drill cuttings stockpiled on the north end of the Location. Berm has been installed in a manner that is inadequate to contain/prevent a spill. BMP also largely unconsolidated material.



August 4, 2023

Photo 4: Photo taken from the north end of the Location, just north of the Location's cutslope. Photo shows Operator has pushed cutting material beyond the working pad surface and cutslope.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Photo 5: Photo taken from the north end of the Location, just north of the Location's cutslope. Photo shows Operator has pushed cutting material beyond the working pad surface and cutslope.



Photo 6: Drone imagery of the Location. Photo shows Operator has pushed cutting material beyond the working pad surface and cutslope (arrow).



Photo 7: Drone imagery of the Location. Photo shows Operator has pushed cutting material beyond the working pad surface and cutslope (dotted line).

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location Number: 383264



Photo 8: Photos example showing stained soils on the west end of the Location.



Photo 9: Photo example showing silt fence on the Location has not been maintained in accordance with good engineering practices.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location Number: 383264



Photo 10: Photos example showing silt fence and erosion logs on the Location has not been maintained in accordance with good engineering practices.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



August 4, 2023

Photo 11: Photo taken from the topsoil stockpile on the north end of the Location. Photo shows BMPs to prevent weed establishment on the topsoil stockpiles are inadequate.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



August 4, 2023

Photo 12: Photo shows topsoil stockpile on the west end of the Location. Photo shows BMPs to prevent weed establishment on the topsoil stockpiles are inadequate.