

Inspection Photos  
Location Name: Hilcorp Allison Unit Com 63  
Location ID: 067-08373



Photo #1. Overview of the well location.

Inspection Photos  
Location Name: Hilcorp Allison Unit Com 63  
Location ID: 067-08373



Photo #2. View of the wellhead assembly.

Inspection Photos  
Location Name: Hilcorp Allison Unit Com 63  
Location ID: 067-08373



Photo #3. View of the #138 wellhead assembly.

Inspection Photos  
Location Name: Hilcorp Allison Unit Com 63  
Location ID: 067-08373



Photo #4. View of unmarked guyline anchor.