

Inspection Photos

API: 071-09590

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/7/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09590 | Date: 8/7/2023

Inspection Photos



Photo 1. Facing southwest toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09590 | Date: 8/7/2023

Inspection Photos



Photo 2. Facing toward the cut slope which has been repaired, seeded, and hydromulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09590 | Date: 8/7/2023

Inspection Photos



Photo 3. There is still oil stained soil around the engine skid .



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09590 | Date: 8/7/2023