

Inspection Photos

API: 071-06324

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/7/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06324 | Date: 8/7/2023

Inspection Photos



Photo 1. Facing southeast toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06324 | Date: 8/7/2023

Inspection Photos



Photo 2. Facing east at the location. The erosion gully has been repaired and rock rip/rap BMP's were installed. Disturbed areas have been seeded and hydromulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06324 | Date: 8/7/2023