

Final Reclamation Inspection

August 1, 2023

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 305367

Inspection Document #: 697504779

Weld County, CO

NENE Section 30 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: BETZ #30-11
Location ID: 305367



Photo 1. Google Earth aerial imagery from 5/24/2023 illustrates the approximate location where an Operator representative traveled the wrong way during PA operations for Betz #30-11 got stuck, which created ruts.



Photo 2. Photo evidence of truck and trailer which got stuck creating ruts.



Photo 3. Photo evidence of truck and trailer which got stuck creating ruts.