

**Operator: CRESTONE PEAK RESOURCES OPERATING LLC**

**Location Name: PURITAN 2N68W/34SESE**

**Loc ID: 336413**

**Inspection: 710100014**



**Exhibit A**



**Exhibit B**

**CA:** Unused equipment (fiberglass storage tank, steel aboveground storage tank, piping, corrugated steel containment, etc.) is being stored on location. Comply with Rule 606.a.

**CA Resolution:** Field reports that equipment has now been removed from the location after completing scheduled work, and samples have been taken of the open excavations. It was also noted that there is fencing that remains on the location but will be removed by either the purchaser or Field by 8/9/2023.