

Box Elder K #2 and K 1-3 Tank Battery
Remediation Project
Photographic Log
City and County of Denver



Photo 1: Box Elder K #2 and K 1-3 tank battery former pit tank excavation area, 7/21/2023.



Photo 2: SS10 collected from the base of the excavation area, 7/18/2023.

Box Elder K #2 and K 1-3 Tank Battery
Remediation Project
Photographic Log
City and County of Denver



Photo 3: SS11 collected from the north sidewall of the excavation area, 7/19/2023.



Photo 4: SS12 collected from the west sidewall of the excavation area, 7/19/2023.

Box Elder K #2 and K 1-3 Tank Battery
Remediation Project
Photographic Log
City and County of Denver



Photo 5: SS13 collected from the east sidewall of the excavation area, 7/20/2023.



Photo 6: SS14 collected from the south sidewall of the excavation area, 7/20/2023.