

# Interim Reclamation and Stormwater Inspection

August 3, 2023

Operator: UPLAND EXPLORATION LLC- #10701

Location ID: 462919

Inspection Document #: 697504783

Weld County, CO

SESE Section 21 T11N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Little Lady 21/South Well Pad  
Location ID: 462919



**Photo 1.** Photo taken from the southeastern location, facing North. Photo illustrates much of the vegetative growth to be an introduced grass species, which was falsely reported to Staff.

Red circle is highlighting an undesirable, introduced invasive plant species, Cereal rye. Cereal rye was observed throughout portions of the interim reclamation area.



**Photo 2.** Close up photo taken of Cereal rye.



Inspection Photos

Location Name: Little Lady 21/South Well Pad

Location ID: 462919



**Photo 3.** Photo taken from the southeastern location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the southwestern location, facing North. See comments under Photo 1.



Inspection Photos  
Location Name: Little Lady 21/South Well Pad  
Location ID: 462919



**Photo 5.** Photo taken from the southern interim reclamation area, facing West. Photo illustrates reference vegetation to the left of the red-dashed line and the introduced grass species to the right, which is not reflective of reference areas.



## Inspection Photos

Location Name: Little Lady 21/South Well Pad

Location ID: 462919



**Photo 6.** Photo taken from the topsoil stockpile, facing East. It is hard to demonstrate in this photo but there is desirable germination.



**Photo 7.** Close up photo taken from the topsoil stockpile illustrating desirable germination of what appears to be native grass.

Note- there is some undesirable weed establishment that will have to be controlled at a future date.

