

Inspection Photos

Location Name: North Lost Creek-63N62W 20SWNE Tank Battery

Location ID: 331757



Location & missing battery sign & Overgrown vegetation




Pit missing capacity and NFPA placards

Inspection Photos

Location Name: North Lost Creek-63N62W 20SWNE Tank Battery

Location ID: 331757



Gas meter run/ pig station & Overgrown vegetation




Location & Missing battery sign & Overgrown vegetation

Inspection Photos

Location Name: North Lost Creek-63N62W 20SWNE Tank Battery

Location ID: 331757



Unmarked Risers



Unmarked Riser