


Inspection Photos  
Location Name: Struckmeyer 6-22-5-45  
API Number: 125-10815



1. Well sign on Meter Shed.



2. View of Wellhead. Note vegetation.

**Inspection Photos**  
**Location Name: Struckmeyer 6-22-5-45**  
**API Number: 125-10815**



**3. Concrete pad left on location after Pump Jack removed.**  
**Note vegetation.**



**4. Meter Shed.**

**Inspection Photos**  
**Location Name: Struckmeyer 6-22-5-45**  
**API Number: 125-10815**




**5. View of inlet valve from well to Meter Shed.**




**6. View of outlet valves from Gas Meter and Separator.**

**Inspection Photos**  
**Location Name: Struckmeyer 6-22-5-45**  
**API Number: 125-10815**



**7. View of Chart in Meter Box at time of inspection.**



**8. View of Meter Calibration/Test Log inside Meter Shed at time of inspection.**

**Inspection Photos**  
**Location Name: Struckmeyer 6-22-5-45**  
**API Number: 125-10815**



**9. Location overview. Note disassembled fencing and vegetation.**



**10. One of four located deadmen with marker down.**