

Inspection Photos

8/4/2023

Operator: NONSUCH NATURAL GAS INC

#10163

Location Number: 324169

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location Number: 324169



Photo 1: Photo taken with a sUAS. Photo shows overview of the Location; reclamation not progressing towards 1003 standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location Number: 324169



Photo 2: Photo taken with a sUAS. Photo shows overview of the Location; reclamation not progressing towards 1003 standards.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location Number: 324169



Photo 3: Photo taken with a sUAS. Photo shows erosion degradation along access road. Stormwater and Erosion control measures remain missing or insufficient to manage runoff in a manner that minimizes erosion, degradation and sediment transport.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location Number: 324169



Photo 4: Photo taken with a sUAS. Photo shows erosion degradation along cut slopes. Stormwater and Erosion control measures remain missing or insufficient to manage runoff in a manner that minimizes erosion, degradation and sediment transport. Slopes/Reclamation not progressing towards 1003 standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location Number: 324169



August 4, 2023

Photo 5: Photo taken from the access road. Photo shows erosion persistent stormwater and erosion degradation; Stormwater and Erosion control measures remain missing or insufficient to manage runoff in a manner that minimizes erosion, degradation and sediment transport.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location Number: 324169



Photo 6: Photo taken with a sUAS. Photo shows pit on the Location; fence remains in disrepair and netting has not been replaced.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location Number: 324169



Photo 7: Photo taken with a sUAS. Photo shows erosion degradation along cut slopes. Stormwater and Erosion control measures remain missing or insufficient to manage runoff in a manner that minimizes erosion, degradation and sediment transport. Slopes/Reclamation not progressing towards 1003 standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location Number: 324169



Photo 8: Photo taken from the pit. Photo shows fence at pit remains in disrepair, and the netting has not been replaced.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location Number: 324169



Photo 9: Photos show wildlife protection BMPs at the secondary containment BMPs remain missing, or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources