

Inspection Photos
Location Name: Bowman 14-21-5-44
API Number: 125-09518



1. View of well open to atmosphere.



2. Production related debris at well.

Inspection Photos
Location Name: Bowman 14-21-5-44
API Number: 125-09518



3. Additional view of open wellbore.



4. Location overview. Note vegetation and nothing marking well.