

# Inspection Photos

API: 071-06204

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/8/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06204 | Date: 8/8/2023

## Inspection Photos



**Photo 1.** Facing southwest along the access road. The erosion along the drainage and road was repaired and stabilized with rock rip-rap.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06204 | Date: 8/8/2023

## Inspection Photos



**Photo 2.** Facing southwest toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

API: 071-06204 | Date: 8/8/2023