

Inspection Photos
Location Name: CAERUS PICEANCE LLC F17E Pad
Location #: 334793



Photo # 5435 From entrance to location



Photo # 5436 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC F17E Pad
Location #: 334793



Photo # 5437 Location



Photo # 5438 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC F17E Pad
Location #: 334793



Photo # 5439 Location



Photo # 5444 Improperly marked deadman