

Inspected Facilities

Facility ID: 443794 Type: TANK API Number: - Status: AC Insp. Status: AC

COGCC Comments

Comment	User	Date
Follow up inspection to Doc# 702402123 in response to FIRR #403489276. Based on photos submitted be operator corrective actions are complete. (Photos attached to FIRR)	revasr	08/10/2023