

Inspection Photos
Location Name: CAERUS PICEANCE LLC E17E Pad
Location #: 334898



Photo # 5132 From entrance to location



Photo # 5133 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC E17E Pad
Location #: 334898



Photo # 5134 Location



Photo # 5135 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC E17E Pad
Location #: 334898



Photo # 5136 Location



Photo # 5144 Burner missing cap/wildlife hazard