

# Inspection Photos

8/4/2023

Operator: LARAMIE ENERGY LLC #10433

Location Number: 452807

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location Number: 452807



**Photo 1:** Photo taken from the entrance, on the south side of the Location. Photo shows BMPs to prevent or contain a spill at the porta-johns remain missing or insufficient; units not secured down. Photo also shows that BMPs to ensure that waste remains contained within the sanitary facilities is inadequate; chemicals and fecal material observed spilled onto the working pad surface next to porta-john.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location Number: 452807



**Photo 2:** Continued from photo 1. Photo shows that BMPs to ensure that waste remains contained within the sanitary facilities is inadequate; chemicals and fecal material observed spilled onto the working pad surface next to porta-john.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location Number: 452807



**Photo 3:** Continued from photo 1. Photo shows that BMPs to ensure that waste remains contained within the sanitary facilities is inadequate; chemicals and fecal material observed spilled onto the working pad surface next to porta-john.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location Number: 452807



**Photo 4:** Photo example showing containers missing labeling information per 605 Rules.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location Number: 452807



August 4, 2023

**Photo 5:** Photo example showing containers missing labeling information per 605 Rules.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location Number: 452807



**Photo 6:** Recent winds have blown over a portable light unit, resulting in POLS spilling onto the working pad surface, and impacting stormwater.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location Number: 452807



**Photo 7:** Fluids in containment require removal and proper disposal.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location Number: 452807



**Photo 8:** Stormwater and erosion control measures to minimize erosion and degradation missing or insufficient at slopes adjacent to Location entrance; slopes lack stabilization.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location Number: 452807



**Photo 9:** Stormwater and erosion control measures to minimize erosion and degradation missing or insufficient at slopes adjacent to Location entrance; slopes lack stabilization.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources