

Inspection Photos
Location Name: Shoe 1
API # 05-123-05061



Overgrown vegetation on access road



Inspection Photos
Location Name: Shoe 1
API # 05-123-05061



Well & overgrown vegetation



Sign does not reflect current operator