

## Inspection Photos

Location Name: Shoe-62N62W 21SWSE Tank Battery

Location ID: 317489



**Location**



**Overgrown Vegetation**

## Inspection Photos

Location Name: Shoe-62N62W 21SWSE Tank Battery

Location ID: 317489



August 10, 2023 at 9:43 AM  
+40.1186, -104.3266  
215° SW  
Weld County  
Energy & Carbon Management Commission

**Overgrown Vegetation**



August 10, 2023 at 9:45 AM  
+40.1186, -104.3269  
316° NW  
Weld County  
Energy & Carbon Management Commission

**Overgrown Vegetation & Weathered Berms**



## Inspection Photos

Location Name: Shoe-62N62W 21SWSE Tank Battery

Location ID: 317489



**Overgrown Vegetation & Weathered Berms**

**Overgrown Vegetation & Weathered Berms**



## Inspection Photos

Location Name: Shoe-62N62W 21SWSE Tank Battery

Location ID: 317489



**Overgrown Vegetation & Weathered Berms**



**Overgrown Vegetation & Weathered Berms**



**Inspection Photos**  
**Location Name: Shoe-62N62W 21SWSE Tank Battery**  
**Location ID: 317489**



**Overgrown Vegetation**



**Overgrown Vegetation**



**Inspection Photos**  
**Location Name: Shoe-62N62W 21SWSE Tank Battery**  
**Location ID: 317489**



**No gas meter calibration card**



**No gas meter calibration card**