

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC J23NW Pad
Location #: 335405



Location Overview: Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area. Location is within Rule 411a Surface Water Intermediate Buffer & Rule 411b Generalized Internal Buffer.

Section/Township/Range: 23 6S93W

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC J23NW Pad
Location #: 335405



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC J23NW Pad
Location #: 335405



Photo # 4893 Erosion & transport of sediment on lease road



Photo # 4894 Erosion & transport of sediment on lease road

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC J23NW Pad
Location #: 335405



Photo # 4896 Erosion & transport of sediment on lease road



Photo # 4902 Erosion & transport of sediment on lease road

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC J23NW Pad
Location #: 335405



Photo # 4915 Lack of stabilization/compaction on location



Photo # 4916 Lack of stabilization/compaction on location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC J23NW Pad
Location #: 335405



Photo # 4922 Lack of stabilization/compaction on location



Photo # 4923 Lack of stabilization/compaction on location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC J23NW Pad
Location #: 335405



Photo # 4925 Lack of stabilization/compaction on location



Photo # 4926 Lack of stabilization/compaction on location