

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC I18 Pad**  
**Location #: 334866**



**Photo # 5149 From entrance to location**



**Photo # 5150 From entrance to location**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC I18 Pad**  
**Location #: 334866**



**Photo # 5151 Location**



**Photo # 5152 Location**



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC I18 Pad**  
**Location #: 334866**



**Photo # 5153 Location**



**Photo # 5154 Location**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC I18 Pad

Location #: 334866



Photo # 5161 Open ended load line

