



**COLORADO OIL & GAS CONSERVATION COMMISSION  
FIELD INSPECTION REPORT**

99999999

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- 009 - 5087		LEASE NAME: VICTOR VERDAA #1-33	
LOCATION: N W N E 33-335-43W		OPERATOR: HANKS	
DATE: 1-13-97		INSPECTOR: R. Van Liche	
Insp. Type: HR	Insp. Status: PA	PA: (Y) N	Pass/Fail: (P) F
		Viol.: Y (N)	NOV: Y (N)

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210)		
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904)		
<b>Fences</b> (Rule 604.C.(3), 1003.A)		
<b>Tank Battery Equipment</b> (Rule 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 604)		
<b>General Housekeeping</b> (Rule 603.G)		
<b>Spills (Oil/Water)</b> (Rule 908)		
<b>Bradenhead</b> (Rule 207)		
<b>Drilling Well/Workover</b> (Rule 315)		
<b>Surface Rehabilitation</b> (Rule 317)	<i>Reclaimed, grass.</i>	
<b>Miscellaneous</b>		

**CORRECTIVE ACTION REQUIRED:** *None*

**Date Corrective Action Required By:** \_\_\_\_\_ **Date Remedied:** \_\_\_\_\_

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site

