

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SWNW

Location ID: 334807

Date: 8/8/2023



South End of Location – Photo #05697



North End of Location – Photo #05698

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SWNW

Location ID: 334807

Date: 8/8/2023



Wellheads – Photo #05699



Separators – Photo #05703

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SWNW

Location ID: 334807

Date: 8/8/2023



Tank Battery – Photo #05700



Check Dam Needs Maintenance – Photo #05707

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SWNW

Location ID: 334807

Date: 8/8/2023



Check Dam Needs Maintenance – Photo #05708