

Inspection Photos
Location Name: CAERUS PICEANCE LLC I13 Pad
Location #: 334665



Photo # 5189 From entrance to location



Photo # 5190 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC I13 Pad
Location #: 334665



Aug 8, 2023 at 10:06:06 AM
CO



Aug 8, 2023 at 10:06:28 AM
CO

Photo # 5191 Location

Photo # 5192 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC I13 Pad
Location #: 334665



Photo # 5193 Location



Photo # 5204 Stained gravel

Inspection Photos
Location Name: CAERUS PICEANCE LLC I13 Pad
Location #: 334665



Photo # 5205 Stained gravel