

Inspection Photos
Location Name: Rohn 9-60-14A PAD
Location ID: 457136



Photo 1 – Sign at Entrance



Photo 2 – Well Flowline

Inspection Photos
Location Name: Rohn 9-60-14A PAD
Location ID: 457136



Photo 3 – Wellheads



Photo 4 – LACT

Inspection Photos
Location Name: Rohn 9-60-14A PAD
Location ID: 457136



Photo 5 – Tank Battery



Photo 6 – ECD and Separator

Inspection Photos
Location Name: Rohn FED 1324 PAD
Location ID: 461117



Photo 7 – Separators



Photo 8 – Compressor



Inspection Photos
Location Name: Rohn FED 1324 PAD
Location ID: 461117



Photo 9 – Separator and Air Unit



Photo 10 – Unused Equipment in NW Corner

Inspection Photos
Location Name: Rohn FED 1324 PAD
Location ID: 461117



Photo 11 – Tanks on South Side of Location