

**Inspection Photos**  
**Location Name: Peggy 2501 PAD**  
**Location ID: 462872**



**Photo 1 – Sign at Entrance**



**Photo 2 – LACT**



**Inspection Photos**  
**Location Name: Peggy 2501 PAD**  
**Location ID: 462872**



**Photo 3 – Wellheads**



**Photo 4 – Bulk Tank**



**Inspection Photos**  
**Location Name: Peggy 2501 PAD**  
**Location ID: 462872**



**Photo 5 – Tank Battery**



**Photo 6 – Unused Equipment in NW Corner**

**Inspection Photos**  
**Location Name: Peggy 2501 PAD**  
**Location ID: 462872**



**Photo 7 – Compressor**



**Photo 8 – Separators**



**Inspection Photos**  
**Location Name: Peggy 2501 PAD**  
**Location ID: 462872**



**Photo 9 – Gas Meter Houses**



**Photo 10 – Air Unit**

**Inspection Photos**  
**Location Name: Peggy 2501 PAD**  
**Location ID: 462872**



**Photo 11 – VRUs**



**Photo 12 – Separators and Heater Treater**



**Inspection Photos**  
**Location Name: Peggy 2501 PAD**  
**Location ID: 462872**



**Photo 13 – Gas Lift Injection Meters**



**Photo 14 – Well Flowline Headers**