

# Inspection Photos

API: 061-06452

Operator: CHEMCO INC

Inspection Date: 8/9/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-06452 - Date: 8/9/2023

## Inspection Photos



**Photo 1.** Facing northwest toward the tan battery.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06452 - Date: 8/9/2023

## Inspection Photos



**Photo 2.** There is oil stained soils near the tank at the red arrow. There is an unused pipe riser at the yellow arrow and various plastic debris.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06452 - Date: 8/9/2023

## Inspection Photos



**Photo 3.** Facing southwest toward the pumpjack and vertical separator. There is no secondary containment around the separator tank.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06452 - Date: 8/9/2023

## Inspection Photos



**Photo 4.** There is oil saturated soils at the base of the separator approximately 4ft. X4ft. Oil soils need to be cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06452 - Date: 8/9/2023

## Inspection Photos



**Photo 5.** There is wood posts and barbed wire laying on the ground which needs to be removed..



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06452 - Date: 8/9/2023

## Inspection Photos



**Photo 6.** Facing toward the wellhead. There is oil stained soils around the wellhead which needs to be cleaned up. Area impacted is approx. 20ft.x8ft.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06452 - Date: 8/9/2023

## Inspection Photos



**Photo 7.** Facing toward the wellhead. There is oil stained soils around the wellhead which needs to be cleaned up. Area impacted is approx. 20ft.x8ft. There is oil sludge shown at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06452 - Date: 8/9/2023

## Inspection Photos



**Photo 8.** There is unused parts equipment and a container that need to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06452 - Date: 8/9/2023