

# Inspection Photos

API: 061-05143

Operator: WESTERN OPERATING COMPANY

Inspection Date: 8/9/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05143 | Date: 8/9/2023

## Inspection Photos



**Photo 1.** Facing toward the tank battery.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05143 | Date: 8/9/2023

## Inspection Photos



**Photo 2.** Facing south toward the area north of the tank battery where historic spilled occurred and is under remediation. There is mostly annual weedy vegetation but there are some desirable species beginning to establish. Observed some Sand dropseed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05143 | Date: 8/9/2023

## Inspection Photos



**Photo 3.** Facing northwest toward the wellsite.



## Inspection Photos



**Photo 4.** There is oily material being stored in this containment which needs to be removed and properly disposed. This is a potential stormwater and wildlife impact that needs to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05143 | Date: 8/9/2023