

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/14/2023

Submitted Date:

08/14/2023

Document Number:

709700119

**FIELD INSPECTION FORM**Loc ID 440718 Inspector Name: Huck, Keith On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10110

Name of Operator: GREAT WESTERN OPERATING COMPANY LLC

Address: 1775 SHERMAN STREET STE 3000

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

17 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                    | Comment         |
|--------------|-------|--------------------------|-----------------|
| ,            |       | cogccinspection@pdce.com | ALL INSPECTIONS |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name        | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 443366      | WELL | PR     | 11/01/2017  | OW         | 001-09858 | Schaefer 2536-1-4HC  | PR          |
| 443368      | WELL | PR     | 01/01/2019  | OW         | 001-09860 | Schaefer 2413-3-15HN | PR          |
| 443374      | WELL | PR     | 04/01/2019  | OW         | 001-09866 | Schaefer LD 13-031HN | PR          |
| 458703      | WELL | PR     | 04/27/2019  | OW         | 001-10253 | Schaefer LD 13-033HN | PR          |
| 458704      | WELL | PR     | 10/01/2022  | OW         | 001-10254 | Schaefer LD 13-032HC | PR          |
| 458705      | WELL | PR     | 04/27/2019  | OW         | 001-10255 | Schaefer LD 13-032HN | PR          |

**General Comment:**

### Location

Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |              |       |  |
|--------------------|--------------|-------|--|
| <b>Fencing/:</b>   |              |       |  |
| Type               | WELLHEAD     |       |  |
| Comment:           | Cattle Fence |       |  |
| Corrective Action: |              | Date: |  |

|                                   |                                     |       |                 |
|-----------------------------------|-------------------------------------|-------|-----------------|
| <b>Equipment:</b>                 |                                     |       | corrective date |
| Type: Emission Control Device     | # 5                                 |       |                 |
| Comment:                          |                                     |       |                 |
| Corrective Action:                |                                     | Date: |                 |
| Type: Bradenhead                  | # 6                                 |       |                 |
| Comment:                          | All appear to be plumbed to surface |       |                 |
| Corrective Action:                |                                     | Date: |                 |
| Type: Bird Protectors             | # 9                                 |       |                 |
| Comment:                          |                                     |       |                 |
| Corrective Action:                |                                     | Date: |                 |
| Type: Horizontal Heated Separator | # 4                                 |       |                 |
| Comment:                          |                                     |       |                 |
| Corrective Action:                |                                     | Date: |                 |
| Type: Ancillary equipment         | # 1                                 |       |                 |

|   |     |       |
|---|-----|-------|
| Comment: <a href="#">Automation RTU</a> |     | Date: |
| Corrective Action:                      |     | Date: |
| Type: Plunger Lift                      | # 6 |       |
| Comment:                                |     |       |
| Corrective Action:                      |     | Date: |
| Type: VRT                               | # 1 |       |
| Comment:                                |     |       |
| Corrective Action:                      |     | Date: |
| Type: Gas Meter Run                     | # 2 |       |
| Comment:                                |     |       |
| Corrective Action:                      |     | Date: |
| Type: Compressor                        | # 1 |       |
| Comment:                                |     |       |
| Corrective Action:                      |     | Date: |
| Type: VRU                               | # 2 |       |
| Comment:                                |     |       |
| Corrective Action:                      |     | Date: |
| Type: LACT                              | # 1 |       |
| Comment:                                |     |       |
| Corrective Action:                      |     | Date: |

**Tanks and Berms:**

| Contents                                  | # | Capacity | Type | Tank ID | SE GPS |
|---|---|----------|------|---------|--------|
| CRUDE OIL                                 | 1 | OTHER    |      |         | ,      |
| Comment: <a href="#">Maintenance Tank</a> |   |          |      |         |        |
| Corrective Action:                        |   | Date:    |      |         |        |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |        |
|--------------------|----------|---------------------|---------------------|-------------|--------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |        |
| Comment:           |          |                     |                     |             |        |
| Corrective Action: |          | Date:               |                     |             |        |
| Contents           | #        | Capacity            | Type                | Tank ID     | SE GPS |
| PRODUCED WATER     | 3        | OTHER               |                     |             | ,      |
| Comment:           |          |                     |                     |             |        |
| Corrective Action: |          | Date:               |                     |             |        |

**Paint**

Inspector Name: Huck, Keith

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 533 bbls |  |
| Other (Type)     |          |  |

**Berms**

|                    |                                   |                     |                     |             |       |
|--------------------|-----------------------------------|---------------------|---------------------|-------------|-------|
| Type               | Capacity                          | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Metal              | Adequate                          | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           | Shares berm with production tanks |                     |                     |             |       |
| Corrective Action: |                                   |                     |                     |             | Date: |

|                    |   |          |      |         |                       |       |
|--------------------|---|----------|------|---------|-----------------------|-------|
| Contents           | # | Capacity | Type | Tank ID | SE GPS                |       |
| CRUDE OIL          | 9 | OTHER    |      |         | 39.944863,-104.834929 |       |
| Comment:           |   |          |      |         |                       |       |
| Corrective Action: |   |          |      |         |                       | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 533bbls  |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Wells Served By Facilities Above**

|            |
|------------|
| API Number |
| 001-10254  |
| 001-09866  |
| 001-09858  |
| 001-10253  |
| 001-10255  |
| 001-09860  |

**AirsID**

|            |        |
|------------|--------|
| API Number | AirsID |
|------------|--------|

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

| <b>Inspected Facilities</b>   |                          |  |                   |                         |
|---|--------------------------|--|-------------------|-------------------------|
| Facility ID: <u>443366</u>  | Type: <u>WELL</u>        | API Number: <u>001-09858</u>   | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| <b><u>Producing Well</u></b>  |                          |  |                   |                         |
| Comment: <u>PR</u>  |                          |  |                   |                         |
| Corrective Action:  |                          |  | Date:             |                         |
| Facility ID: <u>443368</u>  | Type: <u>WELL</u>        | API Number: <u>001-09860</u>   | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| <b><u>Producing Well</u></b>  |                          |  |                   |                         |
| Comment: <u>PR</u>  |                          |  |                   |                         |
| Corrective Action:  |                          |  | Date:             |                         |
| Facility ID: <u>443374</u>  | Type: <u>WELL</u>        | API Number: <u>001-09866</u>   | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| <b><u>Producing Well</u></b>  |                          |  |                   |                         |
| Comment: <u>PR</u>  |                          |  |                   |                         |
| Corrective Action:  |                          |  | Date:             |                         |
| Facility ID: <u>458703</u>  | Type: <u>WELL</u>        | API Number: <u>001-10253</u>   | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| <b><u>Producing Well</u></b>  |                          |  |                   |                         |
| Comment: <u>PR</u>  |                          |  |                   |                         |
| Corrective Action:  |                          |  | Date:             |                         |
| Facility ID: <u>458704</u>  | Type: <u>WELL</u>        | API Number: <u>001-10254</u>   | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| <b><u>Producing Well</u></b>  |                          |  |                   |                         |
| Comment: <u>PR</u>  |                          |  |                   |                         |
| Corrective Action:  |                          |  | Date:             |                         |
| Facility ID: <u>458705</u>  | Type: <u>WELL</u>        | API Number: <u>001-10255</u>   | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| <b><u>Producing Well</u></b>  |                          |  |                   |                         |
| Comment: <u>PR</u>  |                          |  |                   |                         |
| Corrective Action:  |                          |  | Date:             |                         |
| <b><u>COGCC Comments</u></b>  |                          |  |                   |                         |
| Comment   |                          |  | User              | Date                    |
| <u>Routine Inspection</u>   |                          |  | <u>huckk</u>      | <u>08/14/2023</u>       |
| <b><u>Attached Documents</u></b>  |                          |  |                   |                         |
| You can go to COGCC Images ( <a href="https://cogcc.state.co.us/webblink/">https://cogcc.state.co.us/webblink/</a> ) and search by document number: |                          |  |                   |                         |
| Document Num  | Description              | URL  |                   |                         |
| <u>709700120</u>  | <u>Inspection Photos</u> | <u>http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6217486</u> |                   |                         |