

# Inspection Photos

API: 061-06392

Operator: CHEMCO INC

Inspection Date: 8/9/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06392 - Date: 8/9/2023

## Inspection Photos



**Photo 1.** Facing toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06392 - Date: 8/9/2023

## Inspection Photos



**Photo 2.** There are oil stained soils at the base of the pumpjack that need to be cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06392 - Date: 8/9/2023

