

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/14/2023

Submitted Date:

08/14/2023

Document Number:

697007890

FIELD INSPECTION FORM

Loc ID 433139 Inspector Name: Peterson, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 370 17TH STREET SUITE 5200
City: DENVER State: CO Zip: 80202

Findings:

35 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427324	WELL	PR	07/01/2018	OW	123-34945	PAVISTMA SOUTH 4	PR
427358	WELL	SI	01/01/2023	OW	123-34959	PAVISTMA SOUTH 5	SI
431531	WELL	SI	06/01/2023	OW	123-36650	PAVISTMA SOUTH 3	SI
431533	WELL	SI	03/01/2023	OW	123-36652	PAVISTMA SOUTH 2	SI
433598	WELL	SI	03/01/2023	OW	123-37703	PAVISTMA SOUTH 1	SI
446111	WELL	PR	02/13/2017	OW	123-43250	Milkshake 23C	PR
452896	WELL	PR	07/29/2018	OW	123-45816	MILKSHAKE 31W-20-8C	PR
452897	WELL	PR	07/29/2018	OW	123-45817	MILKSHAKE 31W-20-4C	PR
452898	WELL	PR	07/29/2018	OW	123-45818	Milkshake 31W-20-15N	PR
452899	WELL	PR	07/29/2018	OW	123-45819	Milkshake 31W-20-9N	PR
452900	WELL	PR	07/29/2018	OW	123-45820	Milkshake 31W-20-3N	PR
452901	WELL	PR	07/29/2018	OW	123-45821	MILKSHAKE 31W-20-12C	PR
452902	WELL	PR	07/29/2018	OW	123-45822	Milkshake 31W-20-7N	PR
452903	WELL	PR	07/29/2018	OW	123-45823	MILKSHAKE 31W-20-10N	PR
452904	WELL	PR	07/29/2018	OW	123-45824	MILKSHAKE 31W-20-14N	PR
452905	WELL	PR	07/29/2018	OW	123-45825	Milkshake 31W-20-11N	PR
452906	WELL	PR	07/29/2018	OW	123-45826	Milkshake 31W-20-13N	PR
452907	WELL	PR	07/29/2018	OW	123-45827	MILKSHAKE 31W-20-6N	PR
452908	WELL	PR	07/29/2018	OW	123-45828	Milkshake 31W-20-5N	PR
453375	WELL	PR	07/29/2018	OW	123-46053	Milkshake 31W-20-16N	PR
453376	WELL	PR	07/29/2018	OW	123-46054	Milkshake 31W-20-1N	PR

453377	WELL	PR	07/01/2018	OW	123-46055	Milkshake 31W-20-2N	PR
453378	WELL	PR	07/29/2018	OW	123-46056	Milkshake 31W-20-17N	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	x 23		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Methanol and chemical systems		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease road entrance		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Soundwalls at compressors		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 20		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 20		

Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Natural gas engine on compressor		
Corrective Action:			Date:
Type: Other	# 4		
Comment:	Hydraulic pumping units		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 20		
Comment:	Bradenhead valves are exposed at surface.		
Corrective Action:			Date:
Type: Emission Control Device	# 6		
Comment:	Pilots are on		
Corrective Action:			Date:
Type: Gas Meter Run	# 6		
Comment:	Calibration cards are current.		
Corrective Action:			Date:
Type: LACT	# 1		
Comment:			
Corrective Action:			Date:
Type: VRU	# 2		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 10		
Comment:	Electric motors on hydraulic pumping units, LACT and VRU's		
Corrective Action:			Date:
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	#		
Comment:	Automation array, solar arrays, ECD scrubbers, methanol and chemical systems in secondary containment, bulk lube oil storage in secondary containment with wildlife protection, electrical systems, supplied air system		
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:	Shared with location #427262		
Corrective Action:			Date:
Type: Bradenhead	# 3		

Comment:	Bradenhead valves are exposed at surface.		Date:	
Corrective Action:			Date:	
Type: Flow Line	# 3			
Comment:			Date:	
Corrective Action:			Date:	
Type: Pig Station	# 3			
Comment:			Date:	
Corrective Action:			Date:	
Type: Gathering Line	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Vertical Separator	# 9			
Comment:			Date:	
Corrective Action:			Date:	
Type: Plunger Lift	# 19			
Comment:			Date:	
Corrective Action:			Date:	
Type: Flow Line	# 20			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:	Maintenance tank				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	<100 BBLS	BV CONCRETE		,
Comment:	60 bbls				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	<50 BBLS	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	8	400 BBLS	STEEL AST		,
Comment:					

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 427324 Type: WELL API Number: 123-34945 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/05/2023 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: _____
 Corrective Action: _____ Date: _____

Facility ID: 427358 Type: WELL API Number: 123-34959 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
 Comment: _____
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/05/2023 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: _____
 Corrective Action: _____ Date: _____

Facility ID: 431531 Type: WELL API Number: 123-36650 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
 Comment: _____
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/05/2023 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: _____
 Corrective Action: _____ Date: _____

Facility ID: 431533 Type: WELL API Number: 123-36652 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/05/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 433598 Type: WELL API Number: 123-37703 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/05/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 446111 Type: WELL API Number: 123-43250 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/08/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 452896 Type: WELL API Number: 123-45816 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Facility ID: 452897 Type: WELL API Number: 123-45817 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 7 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Facility ID: 452898 Type: WELL API Number: 123-45818 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 11 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Facility ID: 452899 Type: WELL API Number: 123-45819 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Facility ID: 452900 Type: WELL API Number: 123-45820 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 452901 Type: WELL API Number: 123-45821 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 452902 Type: WELL API Number: 123-45822 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 452903 Type: WELL API Number: 123-45823 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Facility ID: 452904 Type: WELL API Number: 123-45824 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Facility ID: 452905 Type: WELL API Number: 123-45825 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Facility ID: 452906 Type: WELL API Number: 123-45826 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Facility ID: 452907 Type: WELL API Number: 123-45827 Status: PR Insp. Status: PR

Producing Well

Comment: <u>PR</u>	
Corrective Action:	Date:

BradenHead

Date of Last Brhd Test: 01/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 452908 Type: WELL API Number: 123-45828 Status: PR Insp. Status: PR

Producing Well

Comment: <u>PR</u>	
Corrective Action:	Date:

BradenHead

Date of Last Brhd Test: 01/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 6 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 453375 Type: WELL API Number: 123-46053 Status: PR Insp. Status: PR

Producing Well

Comment: <u>PR</u>	
Corrective Action:	Date:

BradenHead

Date of Last Brhd Test: 01/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 453376 Type: WELL API Number: 123-46054 Status: PR Insp. Status: PR

Producing Well

Comment: <u>PR</u>	
Corrective Action:	Date:

BradenHead

Date of Last Brhd Test: 01/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Facility ID: 453377 Type: WELL API Number: 123-46055 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Facility ID: 453378 Type: WELL API Number: 123-46056 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 6 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Gravel	Pass	Gravel	Pass	Self Inspection	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697007891	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6218310