

Inspection Photos
Location Name: Logos Bondad 33-10 16
Location ID: 067-05599



Photo #1. Overview of well location.

Inspection Photos
Location Name: Logos Bondad 33-10 16
Location ID: 067-05599



Photo #2. View of the wellhead assembly.

Inspection Photos
Location Name: Logos Bondad 33-10 16
Location ID: 067-05599



Photo #3. View of broken power pole.

Inspection Photos
Location Name: Logos Bondad 33-10 16
Location ID: 067-05599



Photo #4. View of gully erosion occurring on location.

Inspection Photos
Location Name: Logos Bondad 33-10 16
Location ID: 067-05599



Photo #5. View of gully erosion occurring on location.