

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RU 28 Pad/Production Facility

Location ID: 335291



Photo # 5734 From entrance to location



Photo # 5735 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RU 28 Pad/Production Facility

Location ID: 335291



Photo # 5737 Location



Photo # 5743 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RU 28 Pad/Production Facility

Location ID: 335291



Photo # 5744 Location



Photo # 5746 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RU 28 Pad/Production Facility

Location ID: 335291



Photo # 5760 Stained soils & gravel



Photo # 5761 Stained soils & gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RU 28 Pad/Production Facility

Location ID: 335291



Photo # 5770 Debris (N/NE area of location)




Photo # 5770 Debris