

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/18-43 Pad

Location ID: 324485

Date: 8/14/2023



SW Corner of Location – Photo #05785



SE Corner of Location – Photo #05786

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/18-43 Pad

Location ID: 324485

Date: 8/14/2023



NE Corner of Location – Photo #05787



NW Corner of Location – Photo #05788

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/18-43 Pad

Location ID: 324485

Date: 8/14/2023



Wellhead – Photo #05789



Wellhead – Photo #05790

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/18-43 Pad

Location ID: 324485

Date: 8/14/2023



Separator – Photo #05793



Separator – Photo #05796

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/18-43 Pad

Location ID: 324485

Date: 8/14/2023



Tank Battery – Photo #05795



Wildlife Protective Equipment Not Effectively Installed – Photo #05791

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/18-43 Pad

Location ID: 324485

Date: 8/14/2023



Debris – Photo #05794



Unprotected Soil Stockpile at Access Road Entrance – Photo #05799

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/18-43 Pad

Location ID: 324485

Date: 8/14/2023



**Unprotected Soil Stockpile at Access Road Entrance – Photo
#05800**