

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/17-13 Pad

Location ID: 324475

Date: 8/14/2023



SW Corner of Location – Photo #05802



NW Corner of Location – Photo #05803

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/17-13 Pad

Location ID: 324475

Date: 8/14/2023



SE Corner of Location – Photo #05804



NE Corner of Location – Photo #05805

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/17-13 Pad

Location ID: 324475

Date: 8/14/2023



Wellhead – Photo #05806

Separator – Photo #05809

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/17-13 Pad

Location ID: 324475

Date: 8/14/2023



Aug 14, 2023 at 11:49:21



Aug 14, 2023 at 11:47:57

Tank Battery – Photo #05810

Bradenhead Valve Not Accessible – Photo #05807

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/17-13 Pad

Location ID: 324475

Date: 8/14/2023



Location Lacks Stabilization – Photo #05811

Location Lacks Stabilization – Photo #05812

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/17-13 Pad

Location ID: 324475

Date: 8/14/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #05814**



Unprotected Soil Stockpile – Photo #05879

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/17-13 Pad

Location ID: 324475

Date: 8/14/2023



Unprotected Soil Stockpile – Photo #05882



Unprotected Soil Stockpile – Photo #05884