

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 19-28 Pad

Location ID: 335259



Photo # 5675 From entrance to location



Photo # 5676 From entrance to location

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC RMV 19-28 Pad
Location ID: 335259



Photo # 5679 Location



Photo # 5680 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 19-28 Pad

Location ID: 335259



Photo # 5681 Location



Photo # 5715 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 19-28 Pad

Location ID: 335259



Photo # 5720 Debris



Photo # 5717 Open ended load line

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC RMV 19-28 Pad
Location ID: 335259



Photo # 5716 Chemical tank label weathered & some info illegible



Photo # 5718 Tank label missing required information