

Final Reclamation Inspection

July 16th, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 323707

Inspection Document #: 701901007

SWNW Section 18 T5N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bright 2
Location ID: 323707




Photo 1. 2023 aerial imagery of the well pad, access road and tank battery (north is up).

Inspection Photos
Location Name: Bright 2
Location ID:323707




Photo 2. Overview photo of the well pad and access road taken with a drone from the southern edge facing north. Photo shows that the access road and well pad appear consistent with the adjacent crop reference area.

Inspection Photos
Location Name: Bright 2
Location ID:323707



Photo 3. Overview photo of the tank battery taken at ground level from the southern edge facing north. Note: tank battery falls on the active Hop well location, location ID 331309. Photo shows that the previous tank battery disturbance is dominated by kochia.