

Final Reclamation Inspection

August 1st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 327580

Inspection Document #: 701901045

NESE Section 21 T6N R66W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Billings 43-21
Location ID: 327580




Photo 1. 2016 aerial imagery of the well pad, access road and associated tank battery (north is up).

Inspection Photos
Location Name: Billings 43-21
Location ID:331144



Photo 2. Overview photo of the well pad and access road taken from the eastern edge facing west using a drone. Photo shows that the well pad and access road appear consistent with adjacent reference area.

Inspection Photos
Location Name: Billings 43-21
Location ID:331144



Photo 3. Overview photo of the tank battery and access road taken from the eastern edge facing west using a drone. Photo shows that the tank battery and access road appear consistent with adjacent reference area.

Inspection Photos
Location Name: Billings 43-21
Location ID:331144



Photo 4. Ground photo of the well pad/tank battery crop field taken from the eastern edge facing west down the tank battery access road.