

# Final Reclamation Inspection

August 2nd, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 306229

Inspection Document #: 701901048

NWNE Section 15 T6N R66W

Corey McDonough  
Reclamation Contractor, COGCC




**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Harvester 31-15  
Location ID: 306229



**Photo 1.** 2023 aerial imagery of the well pad, access road and tank battery (north is up).

Inspection Photos  
Location Name: Harvester 31-15  
Location ID: 306229




**Photo 2.** Overview photo of the well pad taken at ground level from the southern edge facing north.

Inspection Photos  
Location Name: Harvester 31-15  
Location ID:306229



**Photo 3.** Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos  
Location Name: Harvester 31-15  
Location ID:306229



**Photo 4.** Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad appears consistent with the adjacent reference area (see photo #5).

Inspection Photos  
Location Name: Harvester 31-15  
Location ID:306229



Photo 5. Reference area.

Inspection Photos  
Location Name: Harvester 31-15  
Location ID:306229



**Photo 6.** Overview photo of the tank battery taken at ground level from the southern edge facing north. Note: entire southern edge of field does not appear to have been planted with alfalfa. No signs of oil and gas operations.