

Final Reclamation Inspection

August 2nd, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 306300

Inspection Document #: 701901051

SENW Section 10 T6N R63W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Cornish 22-10
Location ID: 306300



Photo 1. 2013 aerial imagery of the well pad and tank battery (north is up).

Inspection Photos
Location Name: Cornish 22-10
Location ID:331144



Photo 2. Overview photo of the tank battery taken from the northern edge facing south.

Inspection Photos
Location Name: Cornish 22-10
Location ID:331144



Photo 3. Cardinal photos taken from the middle of the tank battery.
Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Cornish 22-10
Location ID:331144



Photo 4. Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west. Photo shows that the well pad appears consistent with the adjacent reference area (see photo 5).

Inspection Photos
Location Name: Cornish 22-10
Location ID:331144



Photo 5. Tank battery reference area.



Photo 6. Overview photo of the well pad taken at ground level from the western edge facing east. Photo shows that the well pad appears consistent with adjacent reference area (see photo 5).

Inspection Photos
Location Name: Cornish 22-10
Location ID:331144



Photo 7. Overview photo of the access road. Photo shows that the access road appears reflective of adjacent reference area (see photo 5).