

Final Reclamation Inspection

August 2nd, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 330601

Inspection Document #: 701901053

SWNW Section 29 T6N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Andy 29-2
Location ID: 330601



Photo 1. 2013 aerial imagery of the well pad, access road and tank battery (north is up).

Inspection Photos
Location Name: Andy 29-2
Location ID:330601




Photo 2. Overview photo of the well pad and access road taken with a drone from the southern edge facing north. Photo shows that the well pad and access road appear consistent with adjacent crop reference area.

Inspection Photos
Location Name: Andy 29-2
Location ID:330601




Photo 3. Overview photo of the tank battery taken with a drone from directly above the disturbance. Photo shows that the tank battery has been reclaimed and appears consistent with adjacent reference area.

Inspection Photos
Location Name: Andy 29-2
Location ID:330601



Photo 4. Ground photo of the well pad/tank battery crop field taken at ground level from the southern edge facing north.