

Final Reclamation Inspection

August 2nd, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 323104

Inspection Document #: 701901054

NWSE Section 1 T4N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: FHA 10-1
Location ID: 323104



Photo 1. 2013 aerial imagery of the well pad, access road and tank battery (north is up).

Inspection Photos
Location Name: FHA 10-1
Location ID:323104



Photo 2. Overview photo of the well pad and access road taken with a drone from the southern edge facing north. Photo shows that the access road and well pad appear consistent with adjacent crop reference area.




Photo 3. Overview photo of the tank battery taken with a drone from the southern edge facing north. Photo shows that the tank battery has stunted crop growth and does not appear consistent with adjacent crop reference area.



Photo 4. Ground photo of the well pad and tank battery crop field taken from the northern edge of the tank battery facing southwest.