

Inspection Photos
Location Name: Arndt 27-30HZ
Location ID: 457892



Photo 1: Wellhead




Photo 2: Wellhead



Inspection Photos
Location Name: Arndt 27-30HZ
Location ID: 457892



Photo 3: Wellhead



Photo 4: Wellhead



Inspection Photos
Location Name: Arndt 27-30HZ
Location ID: 457892



Photo 5: Wellhead, DEBRIS



Photo 6: Wellhead, DEBRIS

Inspection Photos
Location Name: Arndt 27-30HZ
Location ID: 457892



Photo 7: Wellhead, DEBRIS




Photo 8: Wellhead, DEBRIS

Inspection Photos
Location Name: Arndt 27-30HZ
Location ID: 457892




Photo 9: Wellhead, DEBRIS

Photo 10: Wellhead, DEBRIS



Inspection Photos
Location Name: Arndt 27-30HZ
Location ID: 457892



Photo 11: Tank Battery



Photo 12: Faded capacity

Inspection Photos
Location Name: Arndt 27-30HZ
Location ID: 457892



Photo 13: Faded capacity




Photo 14: Faded capacity

Inspection Photos
Location Name: Arndt 27-30HZ
Location ID: 457892



Photo 15: Faded capacity



Photo 16: Faded capacity