

Inspection Photos

8/14/2023

Operator: GENESIS GAS & OIL COLORADO LLC
- 10384

Location Number: 414168
Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 414168



Photo 1: Location has not been decompacted, recontoured, regraded and reclaimed in accordance with 1004 Rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 414168



Photo 2: Location has not been decompacted, recontoured, regraded and reclaimed in accordance with 1004 Rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: GENESIS GAS & OIL COLORADO L
Location Number: 414168



Photo 3: Fill slopes of the Location- Location has not been recontoured, regraded and reclaimed in accordance with 1004 Rules. Halogeton established on Location.

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 414168



August 14, 2023

Photo 4: Russian Olive remains established on the Location



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 414168



August 14, 2023



August 14, 2023

Photo 5: Photos weeds have matured and dispersed seeds on the topsoil stockpile. Photo also shows cut slope; Location has not been decompacted, recontoured, regraded and reclaimed in accordance with 1004 Rules. Stormwater and erosion control measures remain missing or insufficient on Location and access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 414168



Photo 6: Example of culvert remaining at access road. Access road has not been decompacted, recontoured, regraded and reclaimed in accordance with 1004 Rules; drainages have not been restored.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 414168



Photo 7: Example of culvert remaining at access road (arrow). Access road (red line) has not been decompacted, recontoured, reggraded and reclaimed in accordance with 1004 Rules; drainage has not been restored



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 414168



Photo 8: Equipment remaining on access road and Location- valve can cellar remains improperly covered.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 414168



August 14, 2023

Photo 9: Photo example showing erosion degradation along access road. Stormwater and erosion control measures remain inadequate. Access road has not been decompacted, recontoured, regraded and reclaimed in accordance with 1004 Rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 414168



August 14, 2023

Photo 10: Photo example showing erosion degradation along access road. Stormwater and erosion control measures remain inadequate. Access road has not been decompacted, recontoured, regraded and reclaimed in accordance with 1004 Rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 414168



Photo 11: Photo example showing erosion degradation along access road. Stormwater and erosion control measures remain inadequate. Access road has not been decompacted, recontoured, regraded and reclaimed in accordance with 1004 Rules. Photo also shows Halogeton establishment on access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 414168



Photo 12: Photo example showing erosion degradation along access road. Stormwater and erosion control measures remain inadequate. Access road has not been decompacted, recontoured, regraded and reclaimed in accordance with 1004 Rules. Photo also shows Halogeton establishment on access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 414168



Photo 13: Photo example showing erosion degradation along access road. Stormwater and erosion control measures remain inadequate. Access road has not been decompacted, recontoured, regraded and reclaimed in accordance with 1004 Rules. Photo also shows Halogeton establishment on access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources