

Inspection Photos
Location Name: Julian A Pluss Unit 1
Location ID: 318666



Pic 1 unable to access wellhead due to crop.

Pic 2 ECD, Separator

Inspection Photos
Location Name: Julian A Pluss Unit 1
Location ID: 318666



Pic 3 GMR, weeds unmanaged.



Pic 4 tanks, weeds unmanaged, stained soil by tanks