

Inspection Photos
Location Name: Vulcan 6-64 10-B 6HN
Location ID: 478811

Aug 15, 2023 at 10:57:27 AM
39.509810,-104.625400
Elbert County
CEMC



Pic 1 chemical tanks do not have control measures in place to protect from stormwater.

Aug 15, 2023 at 10:57:41 AM
39.509810,-104.625400
Elbert County
CEMC



Pic 2 unused equipment needs to be removed from location

Inspection Photos
Location Name: Vulcan 6-64 10-B 6HN
Location ID: 478811



Pic 3 trash on location needs to be removed.



Pic 4 no control measures under chemical tanks.

Inspection Photos
Location Name: Vulcan 6-64 10-B 6HN
Location ID: 478811

Aug 15, 2023 at 10:59:19 AM
39.545808,-104.542399
CEMC



Pic 5 trash on location needs to be removed.

Aug 15, 2023 at 11:00:45 AM
39.546208,-104.542397
CEMC



Pic 6 no wellhead sign on location

Inspection Photos
Location Name: Vulcan 6-64 10-B 6HN
Location ID: 478811

Aug 15, 2023 at 11:01:02 AM
39.546208,-104.542397
CEMC



Pic 7 no wellhead sign, contaminated soil needs to be removed from location.

Aug 15, 2023 at 11:01:20 AM
39.546208,-104.542397
CEMC



Pic 8 no wellhead sign

Inspection Photos
Location Name: Vulcan 6-64 10-B 6HN
Location ID: 478811

Aug 15, 2023 at 11:01:46 AM
39.545165,-104.542287
Elbert County
CEMC



Pic 9 bucket needs to be removed from location, no wellhead sign.

Aug 15, 2023 at 11:05:29 AM
39.545193,-104.542270
Elbert County
CEMC



Pic 10 Tanks

Inspection Photos
Location Name: Vulcan 6-64 10-B 6HN
Location ID: 478811



Pic 11 trash on location needs to be removed



Pic 12 ECD, VRT, VRU.

Inspection Photos
Location Name: Vulcan 6-64 10-B 6HN
Location ID: 478811



Pic 13 electric / generators



Pic 14 Compressor

Inspection Photos
Location Name: Vulcan 6-64 10-B 6HN
Location ID: 478811



Pic 15 Compressor GMR.



Pic 16 Separators