

Interim Reclamation and Stormwater Inspection

Date: 08/09/2023

Operator: OWN RESOURCES OPERATING LLC - 10699

Location ID: 336770

Inspection Document #: 708200456

Yuma County, CO

SESE Section 8 T5N R46W

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: Barber 44-8
Location ID: 336770




Photo 1. The well location does not appear to be progressing towards Rule 1003 regulations and standards. Undesirable vegetation (russian thistle and kochia) was observed to be growing around the location. Active management of undesirable vegetation is required to prevent spread of seed onto adjacent lands.

Inspection Photos
Location Name: Barber 44-8
Location ID: 336770




Photo 2. See comments in Photo 1.

Inspection Photos
Location Name: Barber 44-8
Location ID: 336770



Photo 3. See comments in Photo 1.

Inspection Photos
Location Name: Barber 44-8
Location ID: 336770



Photo 4. See comments in Photo 1.



Photo 5. Unused equipment will need to be replaced on equipment or removed from the location.

Inspection Photos
Location Name: Barber 44-8
Location ID: 336770



Photo 6. See comments in Photo 5.



Photo 7. Debris from the location will need to be removed.