

Final Reclamation and Stormwater Inspection

Date: 08/09/2023

Operator: J W OPERATING COMPANY - 44350

Location ID: 410730

Inspection Document #: 708200457

Yuma County, CO

SENE Section 25 T5N R47W

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: R Korf 3-25
Location ID: 410730



Photo 1. Facing towards the former well location. The presence of road base material was observed throughout the reclaimed portions. All road base material will need to be removed from the location in order to comply with Rule 1004.

Inspection Photos
Location Name: R Korf 3-25
Location ID: 410730



Photo 2. See comments in Photo 1.

Inspection Photos
Location Name: R Korf 3-25
Location ID: 410730



Photo 3. See comments in Photo 1.

Inspection Photos
Location Name: R Korf 3-25
Location ID: 410730




Photo 4. The highlighted portion of the location shows the contrast, or difference, in material (e.g. road base) to that of the adjacent farm ground.

Inspection Photos
Location Name: R Korf 3-25
Location ID: 410730



Photo 5. Undesirable vegetation observed to be growing within the reclaimed area. The location will need to be managed to prevent the spread and establishment of undesirable vegetation. Note: the location will need to be inspected at a future date as the field was currently fallow.

Inspection Photos
Location Name: R Korf 3-25
Location ID: 410730




Photo 6. Taken north of the former well location, looking over the potential salt kill portion identified in previous inspections. A future inspection will be conducted to verify growth when a crop has been planted.