

Inspection Photos

8/14/2023

Operator: GENESIS GAS & OIL COLORADO LLC
- 10384

Location Number: 413496
Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 413496



Photo 1: Photos 1-2 provide an overview of the Location. Photos also show cut slopes of the Location; Location has not been decompacted, recontoured, regraded and reclaimed in accordance with 1004 Rules. Cut slopes lack stabilization.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 413496



August 14, 2023



August 14, 2023

Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 413496



Photo 3: Photo shows erosion degradation, and mass soil migration, has persisted on the cut slopes; control measures to stabilize slopes and manage runoff remain inadequate.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 413496



Photo 4: Photo shows erosion degradation, and mass soil migration, has persisted on the cut slopes; control measures to stabilize slopes and manage runoff remain inadequate.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 413496



Photo 5: Photo shows erosion degradation, and mass soil migration, has persisted on the cut slopes; control measures to stabilize slopes and manage runoff remain inadequate.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 413496



Photo 6: Photos examples showing weeds (Russian Olive) remaining at the Location, and along the access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 413496



Photo 7: Photos examples showing weeds (Russian Olive) remaining at the Location, and along the access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 413496



Photo 8: Photo taken from the fill slopes. Photo shows erosion degradation due to stormwater runoff.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 413496



August 14, 2023

Photo 9: Photo taken from the fill slopes. Photo shows erosion degradation due to stormwater runoff.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 413496



Photo 10: Photo taken from the fill slopes. Photo shows erosion degradation due to stormwater runoff.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 413496



Photo 11: Photo example showing persisting erosion degradation along access road. Stormwater and erosion control measures remain inadequate. Access road has not been decompacted, recontoured, regraded and reclaimed in accordance with 1004 Rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 413496



Photo 12: Photo example showing persisting erosion degradation along access road. Stormwater and erosion control measures remain inadequate. Access road has not been decompacted, recontoured, regraded and reclaimed in accordance with 1004 Rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 413496



Photo 13: Photo example showing persisting erosion degradation along access road. Stormwater and erosion control measures remain inadequate. Access road has not been decompacted, recontoured, regraded and reclaimed in accordance with 1004 Rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 413496



Photo 14: Photo example showing persisting erosion degradation along access road. Stormwater and erosion control measures remain inadequate. Access road has not been decompacted, recontoured, regraded and reclaimed in accordance with 1004 Rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 413496



August 14, 2023

Photo 15 Photo shows riser equipment remaining along access road. Photo also shows access road has not been decompacted, recontoured, regraded and reclaimed in accordance with 1004 Rules



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources